

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2008 Levee Inspection Results**

San Joaquin County Flood Control District

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 01 Littlejohn Creek		Left	2.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/4/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 01 Littlejohn Creek	Left	2.90	06/04/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.00	Earthen Levee	Vegetation			Inspector Comments: GPS local only	37.873793 ° -121.226660 °	37.873793 ° -121.226660 °		1

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 02 Littlejohn Creek		Right	3.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/4/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 02 Littlejohn Creek	Right	3.50	06/04/2008	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.00	Earthen Levee	Vegetation	CR		Inspector Comments: GPS local only	37.875075 ° -121.219897 °	° °		1

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 06 SPRR Drain		Left	0.50

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/4/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 06 SPRR Drain							Left	0.50	06/04/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.00	Earthen Levee	Vegetation	CR	M	Inspector Comments: GPS location only	37.979195 °	37.979195 °		1
								-121.098128 °	-121.098128 °		
2	0.14	0.14	Earthen Levee	Erosion / Bank Caving	WS	A	Note and monitor erosion site.	37.979185 °	37.979185 °		2
								-121.097563 °	-121.097563 °		
3	0.50	0.50	Interior Drainage & Piping Systems	Culverts: Inlets / Outlets	WS	M		37.979550 °	37.979550 °		3
								-121.090090 °	-121.090090 °		

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 07 Bear Creek				Right	16.80
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)	
Date of Inspection	5/14/2008				
DWR Inspector	Herman Phillips				
Accompanied By					
Unit Maintenance Rating (Fall Only)					

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 07 Bear Creek						Right	16.80	05/14/2008		Herman Phillips	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.21	0.35	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.045923 ° -121.371220 °	38.043870 ° -121.370853 °		1
2	1.18	1.18	Earthen Levee	Encroachments	LS	U	Tree or limb	38.043332 ° -121.356323 °	38.043327 ° -121.356207 °		2
3	1.45	1.45	Earthen Levee	Encroachments	LS	U	Landscaping	38.043197 ° -121.351508 °	38.043190 ° -121.351393 °		3
4	5.30	5.30	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.050553 ° -121.286672 °	38.050528 ° -121.286633 °		4
5	5.30	5.30	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.050533 ° -121.286670 °	38.050528 ° -121.286632 °		5
6	6.97	7.13	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.059163 ° -121.261855 °	38.060942 ° -121.259982 °		6
7	6.98	7.13	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.059277 ° -121.261743 °	38.060945 ° -121.259993 °		7
8	9.19	9.20	Earthen Levee	Encroachments	LS	M	Debris	38.070263 ° -121.226575 °	38.070287 ° -121.226353 °		8
9	9.88	9.89	Earthen Levee	Encroachments	LS	M	Tree or limb	38.073110 ° -121.215700 °	38.073133 ° -121.215670 °		9
10	9.97	10.12	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.073660 ° -121.214348 °	38.074138 ° -121.211848 °		10
11	9.98	10.12	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.073697 ° -121.214222 °	38.074138 ° -121.211850 °		11
12	10.01	10.12	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.073815 ° -121.213632 °	38.074142 ° -121.211853 °		12
13	10.42	10.47	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.076087 ° -121.208663 °	38.076682 ° -121.208435 °		13
14	10.95	10.96	Earthen Levee	Encroachments	LS	M	Debris	38.079807 ° -121.201170 °	38.079960 ° -121.201075 °		14
15	11.74	11.78	Earthen Levee	Encroachments	LS	U	Equipment	38.086727 ° -121.190213 °	38.086867 ° -121.189557 °		15
16	12.71	13.15	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.093823 ° -121.176797 °	38.100125 ° -121.176738 °		16
17	13.22	13.91	Earthen Levee	Encroachments	LS	M	Tree or limb	38.100882 ° -121.177485 °	38.109382 ° -121.172740 °		17
18	13.88	13.91	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Regrade the crown roadway for proper drainage.	38.108992 ° -121.172907 °	38.109378 ° -121.172750 °		18
19	14.41	14.57	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.116630 ° -121.172120 °	38.118775 ° -121.171247 °		19

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date	Inspector
Unit No. 07 Bear Creek						Right	16.80	05/14/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	14.59	15.12	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.119007 ° -121.171128 °	38.125695 ° -121.167658 °		20
21	14.70	14.71	Earthen Levee	Encroachments	LS	M	Equipment	38.120417 ° -121.170033 °	38.120468 ° -121.169992 °		21
22	14.99	15.12	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	38.124437 ° -121.169135 °	38.125685 ° -121.167662 °		22

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 08 Bear Creek				Left	16.50
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)	
Date of Inspection	5/16/2008				
DWR Inspector	Herman Phillips				
Accompanied By					
Unit Maintenance Rating (Fall Only)					

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 08 Bear Creek						Left	16.50	05/16/2008		Herman Phillips	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.03	2.29	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042853 ° -121.347548 °	38.042817 ° -121.342943 °		16
2	2.14	2.16	Earthen Levee	Encroachments	LS	CO	Landscaping	38.042862 ° -121.345578 °	38.042843 ° -121.345212 °		18
3	2.19	2.21	Earthen Levee	Encroachments	LS	M	Firewood	38.042860 ° -121.344687 °	38.042842 ° -121.344440 °		17
4	2.36	2.42	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042805 ° -121.341538 °	38.042830 ° -121.340483 °		15
5	2.48	2.52	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042832 ° -121.339403 °	38.042805 ° -121.338695 °		14
6	2.62	2.63	Earthen Levee	Encroachments	LS	PO	Landscaping	38.042762 ° -121.336925 °	38.042717 ° -121.336690 °		13
7	2.68	2.69	Earthen Levee	Encroachments	LS	CO	Landscaping	38.042713 ° -121.336015 °	38.042715 ° -121.335770 °		12
8	2.84	2.87	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042715 ° -121.333063 °	38.042733 ° -121.332573 °		11
9	3.11	3.19	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.042663 ° -121.328143 °	38.042662 ° -121.326678 °		10
10	3.19	3.19	Earthen Levee	Encroachments	LS	U	Firewood	38.042670 ° -121.326820 °	38.042658 ° -121.326675 °		9
11	8.89	8.89	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.067008 ° -121.237393 °	38.067010 ° -121.237392 °		8
12	10.58	10.69	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.074065 ° -121.209862 °	38.074917 ° -121.208357 °		7
13	13.52	13.56	Earthen Levee	Encroachments	LS	U	Landscaping	38.100635 ° -121.176642 °	38.101180 ° -121.177032 °		6
14	13.54	13.59	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.100930 ° -121.176942 °	38.101585 ° -121.177188 °		5
15	15.01	15.07	Earthen Levee	Encroachments	WS	U	Prunings	38.120383 ° -121.169762 °	38.121283 ° -121.169287 °		4
16	15.01	15.18	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.120385 ° -121.169760 °	38.122757 ° -121.169193 °		1
17	15.14	15.15	Earthen Levee	Animal Control	CR	M	Exterminate rodents and backfill and compact or grout burrows.	38.122173 ° -121.169083 °	38.122293 ° -121.169075 °		3
18	15.14	15.18	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.122180 ° -121.169082 °	38.122750 ° -121.169167 °		2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 09 Paddy Creek				Left	1.50
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)	
Date of Inspection	5/14/2008				
DWR Inspector	Herman Phillips				
Accompanied By					
Unit Maintenance Rating (Fall Only)					

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 09 Paddy Creek							Left	1.50	05/14/2008	Herman Phillips	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.09	0.24	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.094585 ° -121.174575 °	38.094940 ° -121.171708 °		3
2	0.57	0.57	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.094888 ° -121.166577 °	38.094892 ° -121.166518 °		1
3	1.45	1.45	Earthen Levee	Vegetation	CR	U	Control annual grass and weeds on the levee slopes and easements.	38.094070 ° -121.150957 °	38.094055 ° -121.150912 °		2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 10 Paddy Creek		Right	1.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 10 Paddy Creek	Right	1.40	05/14/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.53	0.65	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.095290 ° -121.166585 °	38.094792 ° -121.164438 °		3
2	1.01	1.26	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.094697 ° -121.157955 °	38.094318 ° -121.153383 °		2
3	1.39	1.40	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.094340 ° -121.151037 °	38.094340 ° -121.150958 °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles
Unit No. 11 North Paddy Creek	Right	3.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 11 North Paddy Creek						Right	3.60	05/14/2008		Herman Phillips	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.11	0.41	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.096462 ° -121.169247 °	38.100685 ° -121.169113 °		1
2	0.17	0.41	Earthen Levee	Encroachments	LS	U	Crops	38.097342 ° -121.169262 °	38.100685 ° -121.169112 °		3
3	0.17	0.49	Earthen Levee	Encroachments	LS	U	Fences	38.097243 ° -121.169258 °	38.101853 ° -121.168563 °		2
4	0.56	0.57	Interior Drainage & Piping Systems	Culverts: Inlets / Outlets	LS	M		38.102525 ° -121.167733 °	38.102568 ° -121.167598 °		4
5	2.39	2.40	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.118788 ° -121.148453 °	38.118952 ° -121.148285 °		5
6	2.93	3.10	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.125105 ° -121.144097 °	38.126930 ° -121.143227 °		6
7	2.94	3.56	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	38.125143 ° -121.144115 °	38.131945 ° -121.138862 °		7
8	3.15	3.19	Earthen Levee	Encroachments	WS	M	Debris	38.127167 ° -121.142205 °	38.127402 ° -121.141715 °		8

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 12 North Paddy Creek		Left	3.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 12 North Paddy Creek							Left	3.90	05/14/2008	Herman Phillips	
LMR Line	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.00	Interior Drainage & Piping Systems	Culverts: Inlets / Outlets	LS	U		°	°		3
								°	°		
2	0.82	1.04	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.105885 ° -121.165747 °	38.109058 ° -121.165347 °		1
3	1.03	1.07	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.108963 ° -121.165493 °	38.109197 ° -121.165002 °		2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 13 Middle Paddy Creek				Left	1.40
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)	
Date of Inspection	5/14/2008				
DWR Inspector	Herman Phillips				
Accompanied By					
Unit Maintenance Rating (Fall Only)					

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 13 Middle Paddy Creek	Left	1.40	05/14/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.01	1.02	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.110867 ° -121.144188 °	38.110933 ° -121.144072 °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 14 Middle Paddy Creek				Right	1.40

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/14/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date	Inspector
Unit No. 14 Middle Paddy Creek						Right	1.40	05/14/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.25	0.25	Earthen Levee	Closure Structures	WS	M		38.109767 ° -121.155655 °	38.109767 ° -121.155655 °		2
2	0.62	1.32	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Add appropriate gravel or road base. Grade and compact.	38.111753 ° -121.150038 °	38.110943 ° -121.140063 °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway		Bank	Unit Miles
Unit No. 15 Mormon Slough		Right	25.60

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	5/28/2008			
DWR Inspector	Clay Thomas			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 15 Mormon Slough							Right	25.60	05/28/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	11.05	Earthen Levee	Encroachments	LS	M	Prunings	37.962870 ° -121.158385 °	37.962870 ° -121.158385 °		42
2	2.68	2.68	Earthen Levee	Encroachments	LS	M	Prunings	38.030223 ° -121.048407 °	38.030223 ° -121.048407 °		2
3	2.73	2.73	Earthen Levee	Encroachments	LS	PO	Landscaping	38.030185 ° -121.049397 °	38.030185 ° -121.049397 °		3
4	2.88	2.88	Earthen Levee	Encroachments	LS	M	Prunings	38.028572 ° -121.051137 °	38.028572 ° -121.051137 °		4
5	2.99	2.99	Earthen Levee	Encroachments	LS	M	Prunings	38.027547 ° -121.052728 °	38.027547 ° -121.052728 °		5
6	3.04	3.04	Earthen Levee	Encroachments	LS	M	Prunings	38.027270 ° -121.053565 °	38.027270 ° -121.053565 °		6
7	3.11	3.11	Earthen Levee	Encroachments	LS	M	Prunings	38.026527 ° -121.054547 °	38.026527 ° -121.054547 °		7
8	3.19	3.19	Earthen Levee	Encroachments	LS	M	Prunings	38.025712 ° -121.055480 °	38.025712 ° -121.055480 °		8
9	3.26	3.26	Earthen Levee	Encroachments	LS	M	Prunings	38.025053 ° -121.056457 °	38.025053 ° -121.056457 °		9
10	3.30	3.30	Earthen Levee	Encroachments	LS	M	Prunings	38.024735 ° -121.056947 °	38.024735 ° -121.056947 °		10
11	3.34	3.34	Earthen Levee	Encroachments	LS	M	Prunings	38.024362 ° -121.057635 °	38.024362 ° -121.057635 °		11
12	3.40	3.40	Earthen Levee	Encroachments	LS	M	Prunings	38.023913 ° -121.058410 °	38.023913 ° -121.058410 °		12
13	3.50	3.50	Earthen Levee	Encroachments	LS	M	Prunings	38.025052 ° -121.063458 °	38.025052 ° -121.063458 °		14
14	3.61	3.61	Earthen Levee	Encroachments	LS	M	Prunings	38.021818 ° -121.061112 °	38.021818 ° -121.061112 °		13
15	3.92	3.92	Earthen Levee	Encroachments	LS	M	Debris	38.018513 ° -121.064775 °	38.018513 ° -121.064775 °		15
16	4.14	4.14	Earthen Levee	Encroachments	LS	PO	Landscaping	38.016115 ° -121.067187 °	38.016115 ° -121.067187 °		16
17	4.22	4.22	Earthen Levee	Encroachments	LS	M	Material	38.014948 ° -121.067553 °	38.014948 ° -121.067553 °		17
18	4.27	4.27	Earthen Levee	Encroachments	LS	M	Firewood	38.014350 ° -121.067822 °	38.014350 ° -121.067822 °		18
19	4.29	4.29	Earthen Levee	Encroachments	LS	M	Prunings	38.014025 ° -121.067983 °	38.014025 ° -121.067983 °		19

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 15 Mormon Slough						Right	25.60	05/28/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	4.96	4.96	Earthen Levee	Encroachments	WS	M	Equipment	38.005300 ° -121.071863 °	38.005300 ° -121.071863 °		21
21	4.96	4.96	Earthen Levee	Encroachments	LS	M	Equipment	38.005302 ° -121.071867 °	38.005302 ° -121.071867 °		20
22	5.27	5.27	Earthen Levee	Encroachments	WS	M	Debris	38.001543 ° -121.075012 °	38.001543 ° -121.075012 °		22
23	5.34	5.34	Earthen Levee	Encroachments	WS	M	Prunings	38.000793 ° -121.075643 °	38.000793 ° -121.075643 °		23
24	5.38	5.45	Earthen Levee	Encroachments	LS	CO	Buildings	38.000308 ° -121.076133 °	37.999502 ° -121.076835 °		24
25	5.77	5.91	Earthen Levee	Encroachments	WS	U	Debris	37.995733 ° -121.080102 °	37.994185 ° -121.081587 °		25
26	5.91	5.91	Earthen Levee	Animal Control	CR	A	Exterminate rodents and backfill and compact or grout burrows.	37.994307 ° -121.081670 °	37.994307 ° -121.081670 °		26
27	6.37	6.37	Earthen Levee	Erosion / Bank Caving	WS	A	Note and monitor erosion site.	37.988920 ° -121.086368 °	37.988920 ° -121.086368 °		27
28	6.57	10.54	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	37.986653 ° -121.088463 °	37.965040 ° -121.149630 °		28
29	6.61	6.61	Earthen Levee	Encroachments	LS	M	Prunings	37.986128 ° -121.088882 °	37.986128 ° -121.088882 °		29
30	6.96	7.42	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.982623 ° -121.093122 °	37.979147 ° -121.099982 °		30
31	7.60	7.60	Earthen Levee	Encroachments	WS	M	Debris	37.978238 ° -121.102960 °	37.978238 ° -121.102960 °		31
32	7.90	7.90	Earthen Levee	Encroachments	WS	M	Debris	37.975723 ° -121.107205 °	37.975723 ° -121.107205 °		32
33	8.05	8.05	Earthen Levee	Encroachments	WS	M	Debris	37.974337 ° -121.109453 °	37.974337 ° -121.109453 °		33
34	8.26	8.26	Earthen Levee	Encroachments	LS	M	Debris	37.972738 ° -121.112553 °	37.972738 ° -121.112553 °		34
35	8.37	8.80	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	37.971570 ° -121.113675 °	37.969133 ° -121.119958 °		35
36	8.58	8.58	Earthen Levee	Encroachments	LS	M	Prunings	37.969813 ° -121.116218 °	37.969813 ° -121.116218 °		36
37	8.68	8.68	Earthen Levee	Encroachments	LS	U	Equipment	37.969550 ° -121.117927 °	37.969550 ° -121.117927 °		37
38	8.80	8.80	Earthen Levee	Encroachments	LS	M	Equipment	37.969133 ° -121.119957 °	37.969133 ° -121.119957 °		38

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 15 Mormon Slough							Right	25.60	05/28/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	8.84	8.84	Earthen Levee	Encroachments	LS	M	Garbage	37.968730 ° -121.120660 °	37.968730 ° -121.120660 °		39
40	9.63	9.63	Earthen Levee	Encroachments	WS	U	Buildings	37.967017 ° -121.133863 °	37.967017 ° -121.133863 °		40
41	9.69	9.69	Earthen Levee	Encroachments	WS	M	Prunings	37.966662 ° -121.134905 °	37.966662 ° -121.134905 °		41
42	11.05	11.05	Earthen Levee	Encroachments	WS	M	Debris	37.962858 ° -121.158358 °	37.962858 ° -121.158358 °		43
43	12.09	12.09	Earthen Levee	Encroachments	LS	M	Prunings	37.961838 ° -121.176018 °	37.961838 ° -121.176018 °		44
44	12.21	12.21	Earthen Levee	Encroachments	LS	M	Debris	37.961945 ° -121.178268 °	37.961945 ° -121.178268 °		45
45	12.82	12.82	Earthen Levee	Encroachments	WS	M	Prunings	37.961012 ° -121.189067 °	37.961012 ° -121.189067 °		46
46	13.54	13.54	Earthen Levee	Encroachments	LS	M	Equipment	37.960547 ° -121.201300 °	37.960547 ° -121.201300 °		47
47	17.79	18.05	Earthen Levee	Encroachments	LS	PO	Fences	37.990067 ° -121.267757 °	37.991645 ° -121.271827 °		48
48	18.05	18.05	Earthen Levee	Encroachments	LS	PO	Debris	37.991685 ° -121.271847 °	37.991685 ° -121.271847 °		49
49	19.71	19.71	Earthen Levee	Encroachments	LS	PO	Landscaping	37.995272 ° -121.277625 °	37.995272 ° -121.277625 °		50
50	19.80	19.89	Earthen Levee	Encroachments	LS	CO	Landscaping	37.994785 ° -121.279202 °	37.994752 ° -121.280733 °		51
51	20.80	20.91	Earthen Levee	Encroachments	LS	CO	Fences	37.992300 ° -121.296665 °	37.992008 ° -121.298688 °		52
52	20.91	21.01	Earthen Levee	Encroachments	LS	CO	Buildings	37.992015 ° -121.298692 °	37.992103 ° -121.300505 °		53
53	21.03	21.03	Earthen Levee	Encroachments	LS	PO	Landscaping	37.992122 ° -121.300977 °	37.992122 ° -121.300977 °		54
54	21.05	21.10	Earthen Levee	Encroachments	LS	CO	Fences	37.992163 ° -121.301308 °	37.992170 ° -121.302212 °		55
55	21.56	21.75	Earthen Levee	Encroachments	LS	PO	Landscaping	37.987718 ° -121.307630 °	37.985305 ° -121.309322 °		56
56	22.27	22.32	Earthen Levee	Encroachments	LS	PO	Landscaping	37.980533 ° -121.316473 °	37.980285 ° -121.317410 °		57
57	24.22	25.62	Earthen Levee	Encroachments	LS	PO	Landscaping	37.974485 ° -121.347958 °	37.975337 ° -121.372153 °		58

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 16 Mormon Slough				Left	23.70
	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)	
Date of Inspection	6/3/2008				
DWR Inspector	Clay Thomas				
Accompanied By					
Unit Maintenance Rating (Fall Only)					

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 16 Mormon Slough						Left	23.70	06/03/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.07	2.07	Earthen Levee	Encroachments	WS	CO	Debris	38.034930 ° -121.041238 °	38.034930 ° -121.041238 °		49
2	5.44	6.35	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees over roadway to at least 12 feet above ground level.	37.998763 ° -121.076837 °	37.988295 ° -121.086257 °		48
3	6.36	6.36	Earthen Levee	Erosion / Bank Caving	WS	M	Note and monitor erosion site.	37.988240 ° -121.086358 °	37.988240 ° -121.086358 °		47
4	11.41	11.41	Earthen Levee	Encroachments	LS	M	Debris	37.960588 ° -121.163393 °	37.960588 ° -121.163393 °		46
5	12.95	13.15	Earthen Levee	Encroachments	LS	M	Agricultural Ditch	37.960232 ° -121.190930 °	37.959405 ° -121.194278 °		45
6	13.55	13.55	Earthen Levee	Encroachments	LS	PO	Debris	37.959897 ° -121.200802 °	37.959897 ° -121.200802 °		44
7	16.67	16.67	Interior Drainage & Piping Systems	Flap Gates	WS	U		37.981543 ° -121.249570 °	37.981543 ° -121.249570 °		43
8	19.64	19.64	Earthen Levee	Encroachments	LS	PO	Landscaping	37.991060 ° -121.298593 °	37.991060 ° -121.298593 °		42
9	19.75	19.75	Earthen Levee	Encroachments	LS	PO	Landscaping	37.991008 ° -121.300550 °	37.991008 ° -121.300550 °		41
10	19.76	19.76	Earthen Levee	Encroachments	LS	PO	Landscaping	37.991000 ° -121.300860 °	37.991000 ° -121.300860 °		40
11	19.79	19.79	Earthen Levee	Encroachments	LS	CO	Landscaping	37.991067 ° -121.301430 °	37.991067 ° -121.301430 °		39
12	19.90	19.90	Earthen Levee	Encroachments	LS	PO	Landscaping	37.990975 ° -121.303375 °	37.990975 ° -121.303375 °		38
13	20.02	20.02	Earthen Levee	Encroachments	LS	CO	Fences	37.989660 ° -121.304837 °	37.989660 ° -121.304837 °		37
14	20.05	20.05	Earthen Levee	Encroachments	LS	CO	Fences	37.989382 ° -121.305158 °	37.989382 ° -121.305158 °		36
15	20.08	20.08	Earthen Levee	Encroachments	LS	PO	Landscaping	37.989032 ° -121.305465 °	37.989032 ° -121.305465 °		35
16	20.09	20.09	Earthen Levee	Encroachments	LS	CO	Landscaping	37.988942 ° -121.305548 °	37.988942 ° -121.305548 °		34
17	20.11	20.11	Earthen Levee	Encroachments	LS	PO	Landscaping	37.988632 ° -121.305733 °	37.988632 ° -121.305733 °		33
18	20.15	20.15	Earthen Levee	Encroachments	LS	PO	Landscaping	37.988215 ° -121.305940 °	37.988215 ° -121.305940 °		32
19	20.16	20.16	Earthen Levee	Encroachments	LS	PO	Landscaping	37.988035 ° -121.306035 °	37.988035 ° -121.306035 °		31

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway						Bank	Unit Miles	Inspection Date		Inspector	
Unit No. 16 Mormon Slough						Left	23.70	06/03/2008		Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
20	20.17	20.17	Earthen Levee	Encroachments	LS	PO	Landscaping	37.987907 ° -121.306102 °	37.987907 ° -121.306102 °		30
21	20.18	20.18	Earthen Levee	Encroachments	LS	PO	Landscaping	37.987723 ° -121.306157 °	37.987723 ° -121.306157 °		29
22	20.19	20.19	Earthen Levee	Encroachments	LS	CO	Landscaping	37.987622 ° -121.306230 °	37.987622 ° -121.306230 °		28
23	20.23	20.23	Earthen Levee	Encroachments	LS	CO	Fences	37.987093 ° -121.306495 °	37.987093 ° -121.306495 °		27
24	20.25	20.25	Earthen Levee	Encroachments	LS	CO	Fences	37.986857 ° -121.306602 °	37.986857 ° -121.306602 °		26
25	21.17	21.17	Earthen Levee	Encroachments	LS	CO	Fences	37.978855 ° -121.319108 °	37.978855 ° -121.319108 °		25
26	21.18	21.18	Earthen Levee	Encroachments	LS	CO	Fences	37.978958 ° -121.319258 °	37.978958 ° -121.319258 °		24
27	21.20	21.20	Earthen Levee	Encroachments	LS	CO	Fences	37.979107 ° -121.319415 °	37.979107 ° -121.319415 °		23
28	21.58	21.58	Earthen Levee	Encroachments	WS	PO	Landscaping	37.980918 ° -121.325630 °	37.980918 ° -121.325630 °		22
29	21.64	21.64	Earthen Levee	Encroachments	LS	CO	Landscaping	37.981132 ° -121.326753 °	37.981132 ° -121.326753 °		21
30	21.71	21.71	Earthen Levee	Encroachments	LS	CO	Landscaping	37.981185 ° -121.327822 °	37.981185 ° -121.327822 °		20
31	21.73	21.73	Earthen Levee	Encroachments	LS	PO	Landscaping	37.980972 ° -121.328217 °	37.980972 ° -121.328217 °		19
32	21.74	21.74	Earthen Levee	Encroachments	LS	PO	Landscaping	37.980932 ° -121.328380 °	37.980932 ° -121.328380 °		18
33	21.85	21.85	Earthen Levee	Encroachments	LS	PO	Landscaping	37.980288 ° -121.330173 °	37.980288 ° -121.330173 °		17
34	21.88	21.88	Earthen Levee	Encroachments	LS	PO	Landscaping	37.980178 ° -121.330588 °	37.980178 ° -121.330588 °		16
35	21.90	21.90	Earthen Levee	Encroachments	WS	PO	Landscaping	37.980042 ° -121.330953 °	37.980042 ° -121.330953 °		15
36	21.90	21.90	Earthen Levee	Encroachments	LS	CO	Fences	37.980040 ° -121.330955 °	37.980040 ° -121.330955 °		14
37	21.92	21.92	Earthen Levee	Encroachments	WS	CO	Landscaping	37.979908 ° -121.331383 °	37.979908 ° -121.331383 °		13
38	21.92	21.92	Earthen Levee	Encroachments	LS	CO	Landscaping	37.979905 ° -121.331390 °	37.979905 ° -121.331390 °		12

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway							Bank	Unit Miles	Inspection Date	Inspector	
Unit No. 16 Mormon Slough							Left	23.70	06/03/2008	Clay Thomas	
LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
39	21.97	21.97	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979652 ° -121.332265 °	37.979652 ° -121.332265 °		11
40	22.01	22.01	Earthen Levee	Encroachments	LS	CO	Landscaping	37.979715 ° -121.332972 °	37.979715 ° -121.332972 °		10
41	22.05	22.05	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979780 ° -121.333647 °	37.979780 ° -121.333647 °		9
42	22.08	22.08	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979820 ° -121.334107 °	37.979820 ° -121.334107 °		8
43	22.13	22.13	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979717 ° -121.335107 °	37.979717 ° -121.335107 °		7
44	22.15	22.15	Earthen Levee	Encroachments	LS	PO	Fences	37.979598 ° -121.335428 °	37.979598 ° -121.335428 °		6
45	22.16	22.16	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979528 ° -121.335620 °	37.979528 ° -121.335620 °		5
46	22.18	22.20	Earthen Levee	Encroachments	LS	CO	Fences	37.979420 ° -121.335815 °	37.979360 ° -121.336188 °		4
47	22.20	22.33	Earthen Levee	Encroachments	LS	PO	Landscaping	37.979367 ° -121.336195 °	37.979368 ° -121.338632 °		3
48	22.57	23.05	Earthen Levee	Encroachments	LS	PO	Urban	37.978012 ° -121.342420 °	37.973158 ° -121.348577 °		2
49	23.06	24.59	Earthen Levee	Encroachments	WS	PO	Urban	37.973135 ° -121.348730 °	37.970950 ° -121.351928 °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 17 Potter Creek				Right	0.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/12/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections****Levee Inspection Report By Mile - Spring 2008****San Joaquin County Flood Control District**

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 17 Potter Creek	Right	0.90	06/12/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								°	°		
								°	°		

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2008 Levee Inspection Results

San Joaquin County Flood Control District

Waterway				Bank	Unit Miles
Unit No. 18 Potter Creek				Left	0.90

	Spring (March - May)	Summer (June - August)	Fall (September - November)	Winter (December - February)
Date of Inspection	6/12/2008			
DWR Inspector	Herman Phillips			
Accompanied By				
Unit Maintenance Rating (Fall Only)				

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2008

San Joaquin County Flood Control District

Waterway	Bank	Unit Miles	Inspection Date	Inspector
Unit No. 18 Potter Creek	Left	0.90	06/12/2008	Herman Phillips

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1								°	°		
								°	°		

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected
--	--	--